## MARITA MWC-1101 / MWC-1103 TABLE SAW

## PRAMOC INDUSTRIALE SPE



MADE IN ITALY

Please read the instructions carefully to ensure the safe and effective use of the tool!

## 1. Technical data

Table size 800 v 550 mm Table height 800 mm

Cutting depth 85 mm Motor speed 2800 rpm

Cutting depth adjustment continuous (0~85 mm)

Bevel cut adjustment continuous (0~45°)

240V-400V Voltage '

Power input 2000W-3000W

Saw blade @ 315 x @30 x 3 0mm 54kg

Weight

## 2.Safety Instructions

Please observe these instructions very carefully to protect yourself and others from possible iniury!

- (1) Set up the circular saw bench on a base that is
- firm.
- level.
- non-slip.
- vibration-free
- Keep the site free of tripping hazards.

Ensure adequate lighting conditions ( >500lux ).

- (2) Do not wear loose fitting clothes. Remove rings, wrist-watch and bracelets. They can be caught in moving parts. Rubber gloves and non-skid footwear are recommended when working outdoors. Wear protecting hair covering to contain long hair.
- (3) Wear ear defenders. Also use face or dust mask if the cutting operation is dusty.
- (4) Keep work area clean. Do not operate the circular saw bench in a moist or wet environment, nor in the vicinity of combustible liquids and gases. Do not use power tools where there is risk to cause fire or explosion
- (5) Persons under the age of 18 are not allowed to operate the circular saw.
- (6) The circular saw must only be operated with all the correctly mounted guards. The supplied splitting wedge must be used. Fig. 19 of the Assembly Instructions shows how the splitting wedge is inserted and reset.
- (7) Never use cracked or distorted saw blades. Only use sharp saw blades.
- (8) Do not use circular saw blades made of high-speed steel ( HSS ).
- (9) The operator is responsible for other people within the working area
- (10)Keep children well away from the circular saw bench, and never leave it unattended. Do not let visitors touch the tool or extension cord. All visitors should be kept away from work area.
- (11)It is impermissible to use wobble saws and groove-milling cutters